

## Version 26 Software Update Details

---

### Problem Fixes in Version 26.0.4 (31-Jul-2023)

#### Install

- Easy-PC used to forget the applied product key after patch or full install.
- 

### Problem Fixes in Version 26.0.3 (28-Jul-2023)

#### Framework

- Antivirus programs used to remove Zipper.dll from Easy-PC installation.

#### Import

- Used to fail to import some Boardmaker files.
- Was hanging whilst opening a particular Ultiboard design.

#### Plotting

- If a milling issue is reported in Plotting, no other plots are created.
- Milling output used to incorrectly check the corner radius against the minimum tool diameter.
- Tented vias used to not be excluded from the plot for PDF and Windows output.

#### ProRouter

- Was unable to route test points.

#### Replace Component

- Used to quit when entering Replace Component in situations where it encounters components not in libraries.

#### Reports

- Application Version in Report Header used to report the wrong application version.
- 

### Problem Fixes in Version 26.0.2 (19-Jun-2023)

#### Apply Layout Pattern

- Apply Layout Pattern did not apply angled tracks.

#### Integrity Check

- Easy-PC used to quite when using Forward Design.

#### Styles

- Merging track styles used to not save when exiting the technology dialog.

#### Values

- Export to CSV from the Component Values dialog used to insert unwanted blanks in the first column.
- 

### Problem Fixes in Version 26.0.1 (25-Jan-2023)

#### BOM Composer

- The BOM Composer used to incorrectly merge totals for different components.

#### CAM/Plots

- The Sign Off Checks dialog used to show unnecessary text.

#### Gerber Import

- Importing a certain Gerber file caused Easy-PC to quit.

#### Groups

- Schematic only group flags were ignored by Integrity Check if the first page did not contain a group.

#### Help

- The index used to show lots of individual entries for 'Plot'. Now they are all under one header.
- More help information has been added for creating User Defined Pads.

**IPC-2581**

- Running IPC-2581 sometimes caused Easy-PC to quit.

**Layers**

- Switching layers with multiple selections across different layers used to cause Easy-PC to quit.