

Version 27 Software Update Details

Problem Fixes in Version 27.0.1 (05-Sep-2023)

BOM Composer

- BOM composer reference names field was incorrect.

Help

- Various help fixes and improvements.

Install

- SnapEDA dockable bar menu link was not visible.
- Using the spice netlist used to display an error stating the spiceio.dll is missing.

Library Tools

- ESC key used to not close the floating library manager dialog.
- New components used to not save to library when using floating library manager.

Start Page

- Start Page links used to not work correctly.

Tools

- Hatched pour at a thermal relief used to cause Easy-PC to quit.
- Transfer to PCB used to not handle combinations of new pin range values.